Energy performance certificate (EPC) recommendation report

Beach Bungalow Alexandra Court Southlands Road Kinmel Bay RHYL LL18 5BG Report number 0220-6228-0440-7310-2034

Valid until **27 February 2030**

Energy rating and EPC

This property's energy rating is C.

For more information on the property's energy performance, see the EPC for this property.

Recommendations

Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Improve insulation on HWS storage.	Low
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	Low
Add optimum start/stop to the heating system.	Medium
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.	Medium
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
Add weather compensation controls to heating system.	Medium
Changes that may pay for themselves within 3 to 7 years	
Changes that may pay for themselves within 3 to 7 years Recommendation	Potential impact on carbon emissions
Recommendation	emissions
Recommendation Add local time control to heating system. Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings	emissions Medium
Add local time control to heating system. Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	emissions Medium Low
Add local time control to heating system. Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required. Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC	emissions Medium Low Medium
Add local time control to heating system. Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required. Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	emissions Medium Low Medium
Add local time control to heating system. Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required. Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Changes that may pay for themselves in over 7 years	emissions Medium Low Medium Medium Potential impact on carbon
Add local time control to heating system. Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required. Some solid walls are poorly insulated - introduce or improve internal wall insulation. Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Changes that may pay for themselves in over 7 years Recommendation	emissions Medium Low Medium Medium Potential impact on carbon emissions

Property and report details

Report issued on	28 February 2020
Total useful floor area	255 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	DesignBuilder Software Ltd, DesignBuilder SBEM, v6.1.0, SBEM, v5.6.a.1

Assessor's details

Assessor's name	Ian Brownley
Telephone	07977494783
Email	ianbrownley@gmail.com
Employer's name	Energy Assessors (Merseyside) Ltd
Employer's address	Ravenswood house 30 Chambres road Southport Merseyside PR8 6JQ
Assessor ID	EES/008579
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Elmhurst Energy Systems Ltd